

Ação de campo FMI
32070-2 – Lista de séries
afetadas – Empresa GE
HEALTHCARE DO BRASIL

Lote/Nº Série
TABY62012
TABY62013
TABY62014
TABY62015
HDGU67501
TABX63301
TABX63302
HDGP50392
HDGP50391
HDGP50390
HDGP50389
HDGP50388
HDGP50393
HDGT50293
HDGT50294
HDHN50877
HDHN50879
HDHN50878
HDHP50309
TABZ70509
HDGU60704
HDGU60705
HDGU60566
HDGU60567
HDGU60568
TABX62942

TABX62943
TABX62967
TABX62968
TABX62969
HDGU60631
HDGK51441
HDGK51442
TABY62021
TABX64022
HDGU60559
TABX62945
HDGU60632
TABX62944
HDGU60463
HDGU60557
HDGU60623
HDGU60624
HDGU60626
HDGU60628
HDGU60629
HDGU60630
HDGV61040
HDGV61042
HDGV61043
HDGV61044
HDGV61045
TABX62939
TABX62940
TABX62941
TABX62965
TABX62966
HDGU60558
HDGU60560

HDGU60561
HDGU60562
HDGU60563
HDGU60564
HDGU60565
HDGU60625
HDGU60627
HDGV61041
TABY62113
HDGU60122
HDGU60123
HDGU60124
HDGU60125
HDGU60126
HDGU60127
HDGU60128
HDGU60129
HDGU60130
HDGU60131
HDGU60132
HDGU60133
HDGV60158
TABX63444
TABX63445
TABX63446
TABX63447
TABX63448
TABX63449
HDGU60052
HDGU60053
HDGU60054
HDGU60055
HDGU60056

HDGU60057
HDGU60058
HDGU60462
HDGR53013
HDGQ51903
HDHQ51008
HDHQ51009
HDHR53058
HDHR53060
HDHR53061
HDGQ50572
HDGS51530
HDGS51531
HDGS51532
HDGS51533
HDGR53241
HDGR53242
HDHR53059
HDGT50557
HDGT50558
HDGQ50571
HDG051902
HDGS52050
HDGT50291
HDGT50292
HDGT50295
HDGT50296
HDGQ51902
HDGR50293
HDGS52050
HDGS52051
HDGS52052
HDGR52626

HDGS52051
HDGS52052
HDGQ50549
HDGQ50550
HDGQ50551
HDGQ50553
HDGQ50554
HDGQ50555
HDGQ50556
HDGQ50558
HDGQ50562
HDGQ50564
HDGQ50566
HDGQ50567
HDGQ50568
HDGQ50570
HDGQ50581
HDGT50290
HDGR52955
HDGR52956
HDGS52058
HDGQ51901
HDGR52954
HDGT60315
HDGT60316
HDGQ51900
HDGS51661
HDGQ50569
HDGQ50561
HDGQ50565
HDGM51159
HDGM51160
HDGM51161

HDGM51162
HDGP50304
HDGP50305
HDGQ50552
HDGQ50557
HDGQ50559
HDGQ50560
HDGQ50563
HDGQ50582
HDGT50297
HDGT50298
HDGT50299
HDGS51578
HDGS51579