

ANEXO I - LISTA DOS MODELOS DOS DISPOSITIVOS AFETADOS

Modelos:

BA22-120/I20-40,
BA22-100/I20-40,
BA22-80/I20-40,
BA22-60/I20-40,
BA22-40/I20-40,
BA22-120/I16-40,
BA22-100/I16-40,
BA22-80/I16-40,
BA22-60/I16-40,
BA22-40/I16-40,
BA22-120/I13-40,
BA22-100/I13-40,
BA22-80/I13-40,
BA22-60/I13-40,
BA22-40/I13-40,
BA22-110/I20-30,
BA22-90/I20-30,
BA22-70/I20-30,
BA22-50/I20-30,
BA22-110/I16-30,
BA22-90/I16-30,
BA22-70/I16-30,
BA22-50/I16-30,
BA22-100/I20-55,
BA22-80/I20-55,
BA22-100/I16-55,
BA22-80/I16-55,
BA25-120/I20-40,
BA25-100/I20-40,
BA25-80/I20-40,
BA25-60/I20-40,
BA25-40/I20-40,
BA25-120/I16-40,
BA25-100/I16-40,
BA25-80/I16-40,
BA25-60/I16-40,
BA25-40/I16-40,
BA25-120/I13-40,
BA25-100/I13-40,
BA25-80/I13-40,
BA25-60/I13-40,
BA25-40/I13-40,
BA25-110/I20-30,
BA25-90/I20-30,
BA25-70/I20-30,
BA25-50/I20-30,
BA25-110/I16-30,
BA25-90/I16-30,
BA25-70/I16-30,
BA25-50/I16-30,
BA25-100/I20-55,
BA25-80/I20-55,
BA25-100/I16-55,
BA28-120/I20-40,
BA28-100/I20-40,
BA28-80/I20-40,
BA28-60/I20-40,
BA28-40/I20-40,

BA28-120/I16-40,
BA28-100/I16-40,
BA28-80/I16-40,
BA28-60/I16-40,
BA28-40/I16-40,
BA28-120/I13-40,
BA28-100/I13-40,
BA28-80/I13-40,
BA28-60/I13-40,
BA28-40/I13-40,
BA28-110/I20-30,
BA28-90/I20-30,
BA28-70/I20-30,
BA28-50/I20-30,
BA28-110/I16-30,
BA28-90/I16-30,
BA28-70/I16-30,
BA28-50/I16-30,
BA28-100/I20-55,
BA28-80/I20-55,
BA28-100/I16-55,
BA28-80/I16-55

Números de Lotes:

- Itens acima, fabricados de março de 2011 até o presente momento;
- Itens acima, distribuídos de agosto de 2011 até o presente momento.