

## Produtos afetados - Ação de Campo TC 2018-001

Registro	Nome do produto	Lotes afetados
81246986607	SISTEMA QUIMICO VITROS 5,1 FUSION	34000605; 34000606; 34000835; 34000910; 34001077; 34001382; 34001418; 34001898; 34001991; 34002063; 34002118; 34002125; 34002135; 34002206; 34002217; 34002220; 34002233; 34002243; 34002250; 34002255; 34001457; 34000215; 34000406; 34001322; 34001966; 34002134; 34002248; 34000303; 34000603; 34000621; 34000775; 34000838; 34000857; 34000913; 34001015; 34001917; 34001918; 34001919; 34001936; 34002108; 34002136; 34002202; 34002218; 34002241; 34001323; 34001561; 34001610; 34002119; 34002138; 34001154; 34002209; 34001320; 34002015; 34002201; 34002234; 34002237; 34001632; 34001666; 34002131 e 34001421.
81246986608	SISTEMA QUÍMICO VITROS 4600	46000595; 46000635; 46000680; 46000693; 46000319; 46000185; 46000247; 46000313; 46000399; 46000471; 46000506; 46000509; 46000515; 46000589; 46000457; 46000300; 46000398; 46000463; 46000306; 46000596 e J46000933.
81246982491	SISTEMA QUIMICO VITROS 5600	56001618; 56001767; 56001960; 56002243; 56000245; 56000713; 56000719; 56000721; 56000724; 56000772; 56000773; 56000913; 56000957; 56001009; 56001122; 56001130; 56001457; 56001458; 56001494; 56001528; 56001607; 56001611; 56001657; 56001680; 56001719; 56001794; 56001822; 56001837; 56001853; 56001856; 56001862; 56001889; 56001900; 56001932; 56001941; 56001977; 56001985; 56002001; 56002016; 56002017; 56002055; 56002197; J56002302; 56000385; 56000909; 56000910; 56000949; 56001006; 56001156; 56001169; 56001223; 56001276; 56001290; 56001391; 56001527; 56001538; 56001571; 56001612; 56001653; 56001736; 56001833; 56001836; 56001971; J56002830; 56000283; 56000413; 56000740; 56000330; 56000399; 56000464; 56000758; 56001246; 56000591; 56000759; 56000826; 56001461; 56001490; 56001532; 56001534; 56001620; 56001733; 56001823; 56001984; 56000377; 56000634; 56000697; 56000749; 56001574; 56002244; J56002828 e 56000528.