

90534627FA - Recolhimento Voluntário de Produto Médico - Cateter Angiográfico IMAGER™ II

| Código do Material (Embalagem externa - 5 unidades) | Código do Material (Embalagem interna - individual) | Lote | Número de catálogo | Descrição do Material |
|--|--|-------------|-------------------------------|--------------------------------|
| M001314001 | M001314000 | 57139 | 31-400 | IMAGER II/5/ST/65/038 BX5 |
| M001314001 | M001314000 | 57392 | 31-400 | IMAGER II/5/ST/65/038 BX5 |
| M001314001 | M001314000 | 57709 | 31-400 | IMAGER II/5/ST/65/038 BX5 |
| M001314021 | M001314020 | 57248 | 31-402 | IMAGER II/5/ST/65/035 BX 5 |
| M001314021 | M001314020 | 57533 | 31-402 | IMAGER II/5/ST/65/035 BX 5 |
| M001314071 | M001314070 | 57258 | 31-407 | IMAGER II/5/BERN/40/035 BX 5 |
| M001314081 | M001314080 | 57263 | 31-408 | IMAGER II/5/BERN/40/038 BX5 |
| M001314081 | M001314080 | 57612 | 31-408 | IMAGER II/5/BERN/40/038 BX5 |
| M001314091 | M001314090 | 57242 | 31-409 | IMAGER II/5/BERN/65/035 BX 5 |
| M001314091 | M001314090 | 57243 | 31-409 | IMAGER II/5/BERN/65/035 BX 5 |
| M001314091 | M001314090 | 57510 | 31-409 | IMAGER II/5/BERN/65/035 BX 5 |
| M001314091 | M001314090 | 57530 | 31-409 | IMAGER II/5/BERN/65/035 BX 5 |
| M001314091 | M001314090 | 57531 | 31-409 | IMAGER II/5/BERN/65/035 BX 5 |
| M001314101 | M001314100 | 57173 | 31-410 | IMAGER II/5/BERN/65/038 BX5 |
| M001314101 | M001314100 | 57296 | 31-410 | IMAGER II/5/BERN/65/038 BX5 |
| M001314101 | M001314100 | 57297 | 31-410 | IMAGER II/5/BERN/65/038 BX5 |
| M001314101 | M001314100 | 57381 | 31-410 | IMAGER II/5/BERN/65/038 BX5 |
| M001314101 | M001314100 | 57534 | 31-410 | IMAGER II/5/BERN/65/038 BX5 |
| M001314101 | M001314100 | 57535 | 31-410 | IMAGER II/5/BERN/65/038 BX5 |
| M001314301 | M001314300 | 57238 | 31-430 | IMAGER II/5/SIM1/65/038 BX5 |
| M001314301 | M001314300 | 57389 | 31-430 | IMAGER II/5/SIM1/65/038 BX5 |
| M001314301 | M001314300 | 57697 | 31-430 | IMAGER II/5/SIM1/65/038 BX5 |
| M001314521 | M001314520 | 57383 | 31-452 | IMAGER II/5/CHGB/65/038 BX5 |
| M001314561 | M001314560 | 57130 | 31-456 | IMAGER II/5/CHG2.5/65/038 BX5 |
| M001314561 | M001314560 | 57265 | 31-456 | IMAGER II/5/CHG2.5/65/038 BX5 |
| M001314571 | M001314570 | 57245 | 31-457 | IMAGER II/5/CHG2.5/65/035 BX 5 |

90534627FA - Recolhimento Voluntário de Produto Médico - Cateter Angiográfico IMAGER™ II

| | | | | |
|------------|------------|-------|--------|---|
| M001314581 | M001314580 | 57214 | 31-458 | IMAGER II/5/CONTRA 2/65/038 BX5 |
| M001314581 | M001314580 | 57266 | 31-458 | IMAGER II/5/CONTRA 2/65/038 BX5 |
| M001314581 | M001314580 | 57298 | 31-458 | IMAGER II/5/CONTRA 2/65/038 BX5 |
| M001314581 | M001314580 | 57784 | 31-458 | IMAGER II/5/CONTRA 2/65/038 BX5 |
| M001314591 | M001314590 | 57120 | 31-459 | IMAGER II/5/CONTRA 2/65/035 BX 5 |
| M001314591 | M001314590 | 57617 | 31-459 | IMAGER II/5/CONTRA 2/65/035 BX 5 |
| M001314611 | M001314610 | 57621 | 31-461 | IMAGER II/5/DUCK/65/035 BX 5 |
| M001314661 | M001314660 | 57128 | 31-466 | IMAGER II/5/C2/65/038 BX5 |
| M001314661 | M001314660 | 57708 | 31-466 | IMAGER II/5/C2/65/038 BX5 |
| M001314671 | M001314670 | 57244 | 31-467 | IMAGER II/5/C2/65/035 BX 5 |
| M001314671 | M001314670 | 57783 | 31-467 | IMAGER II/5/C2/65/035 BX 5 |
| M001314681 | M001314680 | 57382 | 31-468 | IMAGER II/5/C2+2 SIDE HOLES/65/038 BX5 |
| M001314691 | M001314690 | 57119 | 31-469 | IMAGER II/5/C2+2 SIDE HOLES/65/035 BX 5 |
| M001314691 | M001314690 | 57695 | 31-469 | IMAGER II/5/C2+2 SIDE HOLES/65/035 BX 5 |
| M001314751 | M001314750 | 57698 | 31-475 | IMAGER II/5/TRAIN/65/038 BX5 |
| M001314761 | M001314760 | 57133 | 31-476 | IMAGER II/5/MIK/65/038 BX5 |
| M001314791 | M001314790 | 57696 | 31-479 | IMAGER II/5/HK1.0/65/035 BX 5 |
| M001314801 | M001314800 | 57580 | 31-480 | IMAGER II/5/SHK0.8/65/038 BX5 |
| M001314811 | M001314810 | 57247 | 31-481 | IMAGER II/5/SHK0.8/65/035 BX 5 |
| M001314821 | M001314820 | 57135 | 31-482 | IMAGER II/5/SHK1.0/65/038 BX5 |
| M001314851 | M001314850 | 57123 | 31-485 | IMAGER II/5/RC1/65/035 BX 5 |
| M001314851 | M001314850 | 57782 | 31-485 | IMAGER II/5/RC1/65/035 BX 5 |
| M001314861 | M001314860 | 57134 | 31-486 | IMAGER II/5/RC2/65/038 BX5 |
| M001314881 | M001314880 | 57268 | 31-488 | IMAGER II/5/RDC/65/038 BX5 |
| M001314881 | M001314880 | 57388 | 31-488 | IMAGER II/5/RDC/65/038 BX5 |
| M001314891 | M001314890 | 57369 | 31-489 | IMAGER II/5/RDC/65/035 BX 5 |
| M001314911 | M001314910 | 57124 | 31-491 | IMAGER II/5/RDC+2 SIDEHOLES/65/035 BX 5 |
| M001314911 | M001314910 | 57600 | 31-491 | IMAGER II/5/RDC+2 SIDEHOLES/65/035 BX 5 |
| M001315001 | M001315000 | 57419 | 31-500 | IMAGER II/4/TENNIS RACQUET/65/035 BX5 |

| 90534627FA - Recolhimento Voluntário de Produto Médico - Cateter Angiográfico IMAGER™ II | | | | |
|---|------------|-------|--------|---------------------------------------|
| M001315031 | M001315030 | 57278 | 31-503 | IMAGER II/5/TENNIS RACQUET/65/035 BX5 |
| M001315061 | M001315060 | 57283 | 31-506 | IMAGER II/5/TENNIS RACQUET/65/038 BX5 |
| M001315061 | M001315060 | 57699 | 31-506 | IMAGER II/5/TENNIS RACQUET/65/038 BX5 |
| M001315091 | M001315090 | 57233 | 31-509 | IMAGER II/4/PIGTAIL/65/035 BX5 |
| M001315091 | M001315090 | 57414 | 31-509 | IMAGER II/4/PIGTAIL/65/035 BX5 |
| M001315091 | M001315090 | 57415 | 31-509 | IMAGER II/4/PIGTAIL/65/035 BX5 |
| M001315101 | M001315100 | 57225 | 31-510 | IMAGER II/4/STRAIGHT/65/035 BX5 |
| M001315101 | M001315100 | 57528 | 31-510 | IMAGER II/4/STRAIGHT/65/035 BX5 |
| M001315131 | M001315130 | 57409 | 31-513 | IMAGER II/5/PIGTAIL/65/038 BX5 |
| M001315131 | M001315130 | 57410 | 31-513 | IMAGER II/5/PIGTAIL/65/038 BX5 |
| M001315161 | M001315160 | 57282 | 31-516 | IMAGER II/5/STRAIGHT/65/038 BX5 |
| M001315161 | M001315160 | 57587 | 31-516 | IMAGER II/5/STRAIGHT/65/038 BX5 |
| M001315191 | M001315190 | 57403 | 31-519 | IMAGER II/5/PIGTAIL/65/035 BX5 |
| M001315191 | M001315190 | 57404 | 31-519 | IMAGER II/5/PIGTAIL/65/035 BX5 |
| M001315201 | M001315200 | 57583 | 31-520 | IMAGER II/5/STRAIGHT/65/035 BX5 |
| M001315251 | M001315250 | 57044 | 31-525 | IMAGER II/4/CONTRALATERAL/65/035 BX5 |
| M001315251 | M001315250 | 57045 | 31-525 | IMAGER II/4/CONTRALATERAL/65/035 BX5 |
| M001315251 | M001315250 | 57046 | 31-525 | IMAGER II/4/CONTRALATERAL/65/035 BX5 |
| M001315281 | M001315280 | 57090 | 31-528 | IMAGER II/5/CONTRALATERAL/65/035 BX5 |
| M001315281 | M001315280 | 57275 | 31-528 | IMAGER II/5/CONTRALATERAL/65/035 BX5 |
| M001315281 | M001315280 | 57581 | 31-528 | IMAGER II/5/CONTRALATERAL/65/035 BX5 |
| M001315281 | M001315280 | 57582 | 31-528 | IMAGER II/5/CONTRALATERAL/65/035 BX5 |
| M001315281 | M001315280 | 57588 | 31-528 | IMAGER II/5/CONTRALATERAL/65/035 BX5 |
| M001315311 | M001315310 | 57279 | 31-531 | IMAGER II/5/CONTRALATERAL/65/038 BX5 |
| M001315311 | M001315310 | 57586 | 31-531 | IMAGER II/5/CONTRALATERAL/65/038 BX5 |
| M001316021 | M001316020 | 57706 | 31-602 | MODEL-IMAGER II/ 4/ ST/65/035 |
| M001316071 | M001316070 | 57375 | 31-607 | MODEL-IMAGER II/ 4/ BERN/40/035 |
| M001316091 | M001316090 | 57215 | 31-609 | MODEL-IMAGER II/ 4/ BERN/65/035 |
| M001316091 | M001316090 | 57602 | 31-609 | MODEL-IMAGER II/ 4/ BERN/65/035 |

| 90534627FA - Recolhimento Voluntário de Produto Médico - Cateter Angiográfico IMAGER™ II | | | | |
|---|------------|-------|--------|--|
| M001316091 | M001316090 | 57603 | 31-609 | MODEL-IMAGER II/ 4/ BERN/65/035 |
| M001316311 | M001316310 | 57608 | 31-631 | MODEL-IMAGER II/ 4/ SIM1/65/035 |
| M001316531 | M001316530 | 57578 | 31-653 | MODEL-IMAGER II/ 4/ CHGB/65/035 |
| M001316551 | M001316550 | 57579 | 31-655 | MODEL-IMAGER II/ 4/ CHGC/65/035 |
| M001316581 | M001316580 | 57376 | 31-658 | MODEL-IMAGER II/ 4/ CONTRA 2/65/035 |
| M001316581 | M001316580 | 57526 | 31-658 | MODEL-IMAGER II/ 4/ CONTRA 2/65/035 |
| M001316581 | M001316580 | 57527 | 31-658 | MODEL-IMAGER II/ 4/ CONTRA 2/65/035 |
| M001316691 | M001316690 | 57577 | 31-669 | MODEL-IMAGER II/4/C2+2 SIDE HOLES/65/035 |
| M001316851 | M001316850 | 57378 | 31-685 | MODEL-IMAGER II/ 4/ RC1/65/035 |