

Número de série dos monitores afetados

19118	7661D	8820D
19227	7716D	8844D
19308	7729D	8954D
19313	7757D	9000D
19315	7777D	9023D
19316	7798D	9026D
19319	7843D	9028D
19321	7856D	9033D
19323	7863D	9038D
19325	8002D	30509L
19326	8011D	30523L
19327	8016D	30528L
19329	8018D	30537L
19330	8125D	30539L
192288	8158D	30542L
20371D	8164D	30557L
20405D	8166D	30578L
20411D	8179D	30584L
20422D	8181D	30590L
20736D	8185D	30592L
20737D	8190D	30608L
20766D	8193D	30622L
20770D	8198D	30632L
20771D	8208D	30644L
21047D	8209D	30645L
21048D	8213D	30652L
21072D	8214D	30655L
21073D	8229D	30657L
21077D	8249D	50144V
21081D	8251D	A0785L
21084D	8253D	A0791L
21085D	8254D	A0811L
21087D	8259D	A0824L
21090D	8275D	A0835L
21091D	8278D	A0846L
21092D	8287D	A0857L
21781D	8292D	30980L
21805D	8294D	30837L
21812D	8296D	8227D
21820D	8423D	
21842D	8437D	
21858D	8439D	
22190D	8445D	
22198D	8455D	
22206D	8489D	
22208D	8491D	
22211D	8496D	
5606D	8667D	
6006D	8705D	
6314D	8709D	
7512D	8712D	
7639D	8732D	
7640D	8735D	
7649D	8805D	