

Ação de Campo – 1474858 – Códigos/Lotes afetados

Código	Batch
CDH29A	R40863
CDH33A	R40D9T
CDH21A	R40E9V
CDH21A	R40M38
CDH25A	R40F4J
CDH25A	R40H19
CDH25A	R40H3T
CDH25A	R40M0T
CDH29A	R40819
CDH29A	R4096J
CDH29A	R4096Y
CDH29A	R40J9J
CDH29A	R40L4V
CDH29A	R40M07
CDH29A	R40M22
CDH29A	R40N8N
CDH29A	R40X7M
CDH29A	R41164
CDH29A	R41194
CDH29A	R4145H
CDH33A	R4075V
CDH33A	R40A5L
CDH33A	R40A9W
CDH33A	R40L8Z
CDH33A	R40P9C
CDH33A	R40R3F
CDH25A	R57549
CDH29A	R4081K
CDH29A	R40E2A
CDH29A	R40E2V
CDH29A	R40F7Z
CDH29A	R40G47
CDH29A	R40G79
CDH29A	R40G97
CDH29A	R40L57
CDH29A	R40L9J
CDH29A	R40M13
CDH29A	R40M2A
CDH29A	R40N86
CDH29A	R40U4F
CDH29A	R40Z4X
CDH29A	R40Z7T
CDH29A	R40Z7V
CDH29A	R41205
CDH29A	R4121N
CDH29A	R4133U
CDH33A	R4075X

CDH33A	R40F61
CDH33A	R40G3P
CDH33A	R40J0A
CDH33A	R40K31
CDH33A	R40U2P
CDH33A	R40W1E
CDH33A	R40X70
CDH25A	R40D2G
CDH29A	R40813
CDH29A	R40833
CDH29A	R40F3Y
CDH29A	R40G32
CDH29A	R40K7K
CDH29A	R40R30
CDH29A	R40U1N
CDH33A	R40781
CDH33A	R40D5R
CDH33A	R40G4X
CDH33A	R40H1A
CDH33A	R40N54
CDH33A	R40X1X
CDH33A	R40Z81
CDH21A	R40K1D
CDH21A	R40718
CDH21A	R40L7V
CDH21A	R40U9V
CDH21A	R40W23
CDH21A	R40X1T
CDH25A	R40702
CDH25A	R4074U
CDH25A	R40A0Z
CDH25A	R40F3C
CDH25A	R40N79
CDH25A	R40P80
CDH25A	R40R5H
CDH25A	R40R67
CDH25A	R40T7H
CDH25A	R40W8Y
CDH29A	R4080X
CDH29A	R40A8U
CDH29A	R40D6T
CDH29A	R40D8F
CDH29A	R40G91
CDH29A	R40H6W
CDH29A	R40J9D
CDH29A	R40K7T
CDH29A	R40N8P
CDH29A	R40U4L
CDH29A	R40V0C
CDH29A	R4115X

CDH29A	R41336
CDH29A	R41444
CDH29A	R41448
CDH29A	R4145D
CDH29A	R5AW3N
CDH33A	R4077T
CDH33A	R40F8Z
CDH33A	R40M5X
CDH33A	R4112V
CDH33A	R4137D
CDH33A	R4146W
CDH33A	R5AD34
CDH33A	R5AY5V
CDH21A	R5AD4T
CDH25A	T5A53R
CDH25A	R40X3N
CDH25A	R40Z50
CDH25A	R5AC9G
CDH25A	R5C32J
CDH25A	T5A18K
CDH25A	T5A79M
CDH29A	R4193C
CDH29A	T5A74C
CDH29A	R41538
CDH29A	R4153Y
CDH29A	R41564
CDH29A	R41565
CDH29A	R41703
CDH29A	R4170F
CDH29A	R4186N
CDH29A	R41962
CDH29A	R5C505
CDH29A	T40189
CDH29A	T5A311
CDH29A	T5A48U
CDH33A	T4037C
CDH33A	R4146X
CDH33A	R41579
CDH33A	R4170T
CDH33A	R4183E
CDH33A	R41878
CDH33A	T4022H
CDH33A	R40K32